OUT60683

Sanifized!

CROUP 1
Excluded from auton
downgrading and
declassification

P 162241Z DEC 66
FM NPIC WASHDC
TO RUCSAAA/SAC OFFUTT AFB OMAHA NEB
RUCVAAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
RUCVAAA/2D RTS BARKSDALE AFB LA
RUEKDA/DIA WASHDC
RUCIJRA/NAVRECONTECHSUPPCEN SUITLAND MD
RUEPIA/CIA WASHDC
RUWBKNA/15TH AF MARCH AFB RIVERSIDE CALIF
RUCVAAA/2 AF BARKSDALE AFB LA
BT
S E C R E T CITE NPIC 9347.

15TH AF (FOR DI), SAC (FOR DIM/GLASS LAMP/DOCR, DM 4)
2D AF (FOR DI).

- 1. CAMERA B-15 WAS USED ON MISSION G 935 FLOWN ON 14 DECEMBER

 1966. PROCESSING WAS ACCOMPLISHED BY BARKSDALE AFB.
 - 2. ORIGINAL NEGATIVE:

MADE BETWEEN FRAMES 0299/0300.

- A. DENSITY AND RESOLUTION ARE GOOD.
- B. 9R SIDE: ROLLER CHATTER IS NOTED THROUGHOUT THE MISSION
 ON THE INBOARD EDGE AND INTERMITTENTLY ON FRAMES 0001 THROUGH
 1000 ALONG THE OUTBOARD EDGE. A FINE PLUS DENSITY LINE IS RECORDED
 LONGITUDINALLY 3.8" FROM THE OUTBOARD EDGE ON FRAMES 0301 THROUGH
 0320. A FAINT ROW OF MINUS DENSITY DOTS, 1.7" APART AND 1.0" FROM
 PRODUCT OF THE INBOARD EDGE IS PRESENT ON FRAME 0431 AND CONTINUES THROUGHOUT
 THE MISSION. EMULSION GOUGES AND PINHOLES ARE VISIBLE ON FRAMES
 0599, 0600, 1510, 1801, 2053 AND 2100. A MYLAR TAPE SPLICE WAS
- C. 9L SIDE: ROLLER CHATTER, EDGE STATIC AND EDGE FOG ARE
 PRESENT ON THE INBOARD AND OUTBOARD EDGE THROUGHOUT THE MISSION.
 AN ULTRASONIC SPLICE WAS MADE BETWEEN FRAMES 0299 0300 AND A MANU-

SECRET

Approved For Release 2008/02/21: CIA-RDP78B04558A001500030057-1

-2-

FACTURING SPLICE WAS MADE AT FRAME 2024.

- D. BOTH SIDES: THE MECHANICAL FRAME COUNTER SKIPPED FROM 0002 TO 0004. THE NEGATIVES ARE TITLED SEQUENTIALLY. FRAMES 0001 AND 0002 ARE VERTICALS AND TITLED FRAME 0003 IS A 2R. A DENSITY CHANGE PROBABLY CAUSED BY INTERNAL CAMERA REFLECTION IS VISIBLE APPROXIMATELY 3.0" FROM THE DATA BLOCK EDGE ON SOME VERTICAL FRAMES. THIS ANOMALY HAS BEEN PREVIOUSLY REPORTED. THE FOLLOWING NINE FRAMES DISPLAY VEHICLE INDUCED SMEAR: 0104, 0329, 0331, 0332, 0640, 1035, 1834, 1957 AND 1969. THE LAST TITLED FRAME IS 2257. THE LAST FRAME ON THE DATA BLOCK COUNTER IS 2258.
- E. NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS WERE DETECTED ON THIS MISSION.
 - 3. POSITIVE:
 - A. THE PI SUITABILITY IS GOOD.
 - B. THE PRINTING AND PROCESSING WERE GOOD.
- C. CLOUDS OBSCURED OR DEGRADED APPROXIMATELY 50 PERCENT OF THE MISSION.

GP-1 SECRET

-- END OF MESSAGE --